



**AGNICO EAGLE**

# Committed to Responsible Tailings Management

2023 Tailings Summary Report



# Agnico Eagle's Commitment to Responsible Tailings Management

*Tailings storage facility at Kittilä mine, Finland. View of NP3 and CIL2 cell.*

Agnico Eagle Mines Limited (Agnico Eagle) is a senior Canadian gold mining company that has produced precious metals since 1957. We are committed to the safe and responsible management of our tailings storage facilities.

Our operating mines are located in Australia, Canada, Finland and Mexico, with exploration and development activities in each of these countries as well as in the United States. Agnico Eagle also manages a series of closed mine sites, mainly in Canada.

The geology, operating conditions, climate, and environment of our operating mines and closed mine sites vary considerably. We have adapted our tailings management techniques to respond to the local conditions and risk profiles of each of our sites. This 2023 Tailings Summary Report describes the approach we take to responsibly manage Agnico Eagle's tailings from both a governance and technical perspective. We certify it to be accurate to the best of our knowledge. All significant revisions made to this document since the release of the 2021 Tailings Summary Report, are listed and tracked in Appendix E.



**Michel Julien**  
Vice-President, Environment and Critical Infrastructure

## Tailings: A By-Product of Mining & Mineral Processing

Mines produce “tailings” that must be properly managed and stored to protect the public and the environment. These tailings are a by-product of the mineral processing stage, where valuable metals or minerals, such as gold, are separated from waste rock, and concentrated by either mechanical means (e.g., gravity circuit) or chemical means (e.g., flotation or cyanidation). During the process, water is added to the fine particles of rock to facilitate mineral processing and transport as a slurry. See Appendix A for a more detailed description of each mining stage.


**Tailings** are fine and relatively uniform rock particles mixed with water to form a semi-liquid slurry. They are deposited in **Tailings Storage Facilities (TSF)** for management and storage. In some cases, tailings are dewatered to produce thickened tailings, paste tailings or filtered tailings (in decreasing degree of water content). See Appendix B for definitions of slurry, thickened, paste and filtered tailings. All tailings are unique in grain size and mineral composition. In fact, their physical and chemical behaviour is directly linked to their grain size and mineral composition. Some tailings are inert while others are chemically reactive and must be treated as potentially hazardous due to their capacity to produce acid or to leach trace metals if not properly managed.

# Strengthening Our Tailings Governance for Safe and Responsible Operations

The safe and responsible management of TSFs is a core activity at Agnico Eagle. Since 2018, the company has worked on the development and implementation of a strong governance model for Tailings Management. With the objective of ensuring that a high standard of care is applied from the design phases to closure, Agnico Eagle has developed stringent guidelines that govern management of our TSFs to ensure that all operating and closed infrastructure meet or exceed regulatory requirements and industry standard practices or guidelines.

In 2018, Dr. Michel Julien, Vice President – Environment and Critical Infrastructure, was appointed by Agnico Eagle's Board of Directors to the role of **Accountable Executive Officer** for all Agnico Eagle TSFs. In this oversight role, Dr. Julien reports yearly to the Board of Directors concerning the compliance of our TSFs to regulatory requirements and industry guidelines; as well as confirming that Agnico Eagle's operations have the tools, staff and budget to continue to meet or exceed these standards. **Independent Reviewers** have been appointed to review boards for most of Agnico Eagle's operating sites. These review boards are composed of external, highly reputable, and competent individuals with tailings management expertise. Additionally, **Responsible Persons** and **Engineers of Record** have been identified for all operating sites. Agnico Eagle has taken these actions as part of our company's commitment to the safe and responsible management of our TSFs.

**Figure 1: Governance structure for Agnico Eagle's TSFs**




Agnico Eagle has additionally extended the scope of the governance model to include facilities with similar risk profiles in terms of environmental protection and public safety, such as Heap Leach Facilities (HLF), Water Management Infrastructure (WMI) and Waste Rock Storage Facilities (WRSF). The governance model helps the sites to construct, operate and close the critical infrastructure in a safe and robust manner.

# Incorporating Best Applicable Practices

Agnico Eagle continues to evaluate innovations and technologies for the design and management of TSFs. In that respect, the Company employs an in-house team of qualified professionals and uses reputable engineering and design firms for the development, surveillance, and monitoring of the different facilities.

- Adopting a clear policy on tailings management and a strong commitment by management and our Board of Directors for the safe and responsible management of TSFs.
- Integrating a review process involving internal experts such as an Engineer of Record, and external experts (Independent Review Board) throughout the lifecycle of each mine site.
- Consulting and collaborating with regulatory authorities, stakeholders, and rights holders as an integral part of the design and permitting process.
- Reviewing risks annually, updating risk evaluation methods to more robust processes, and implementing risk mitigation strategies where necessary. See Appendix C for more details regarding the portfolio Risk Evaluation Methodology.
- Rigorous project management standards including Quality Control, Quality Assurance, and formal internal and external reviews to ensure appropriate construction techniques and testing.
- Updating, on a regular basis, the Operating, Monitoring and Surveillance (OMS) Manuals which define the conditions under which each facility is operated as well as the Emergency Response Plans (ERP).
- Establishing best available and applicable practices with respect to statutory inspections and dam safety reviews.
- Installing a robust system of instrumentation to monitor the behaviour of the infrastructure to identify early signs of deviance or anomalies.



# Striving to Meet and Exceed Current Standards and Practices

Agnico Eagle's TSFs are each unique in terms of their site characteristics and contained tailings. Our mines produce conventional slurry, thickened tailings and filtered tailings. Some of these tailings are reused to backfill underground openings after the addition of a binding agent, such as cement. Others are used to construct a cover system as part of the reclamation strategy. This is done wherever possible to reduce the quantity of material that must be managed in each TSF.

Some of Agnico Eagle's TSFs are of recent design, while others have long histories and have evolved over several decades. In some cases, these structures were constructed by other companies and even abandoned for a period of time, prior to being acquired by our company. As a result, some of these sites have experienced varying standards throughout their operating history – from recent design and construction completed under current standards to design and construction over decades of evolving standards and practices. While the history of some of these sites cannot be ignored, TSF performance at all sites must be analyzed in the context of current standards and practices. In some instances, this requires retrofit, operational changes or revised closure plans to ensure the TSF meets current standards and practices.

Table 1 on pages 7 through 23 and notes on pages 24 through 26 contain details regarding Agnico Eagle's tailings storage facilities, including a list of its tailings and storage facility types, containment infrastructure construction method, age, maximum heights, and storage volumes. The table also contains information regarding engineering records and design guidance applied, latest inspections and reviews, remedial actions where required, and risk evaluation results.

Agnico Eagle is committed to progressive improvement of all our TSFs so that they will meet or exceed current standards and that they are operated in line with current best practices. We implement consistent design criteria and operating practices at all our sites and adhere to the guidelines of MAC's Towards Sustainable Mining Tailings Protocol, the Canadian Dam Association (CDA) or the Australian National Committee of Large Dams (ANCOLD). For some of our facilities, these design and operating practices exceed the specific requirements of their particular jurisdiction.

## Types of Tailings

Stored tailings in Agnico Eagle's TSFs do not all present environmental hazards and can even be used to reclaim other contaminated sites that have the potential to generate acid or leach metals – for example, our Goldex mine tailings are being used to reclaim the previously orphaned Manitou site which belongs to the Government of Quebec. Others, meanwhile, can potentially generate acid or leach metals.

Some of Agnico Eagle's sites deposit tailings as a slurry (Kittilä mine), which can release excess water after placement; or as thickened tailings (Canadian Malartic mine), which release only minor amounts of excess water after the placement; or, as filtered tailings (Pinos Altos, LaRonde or Meliadine mines), which do not release excess water after placement. See Appendix B for the definitions of the different types of tailings.



Example of slurry tailings facility  
*Kittilä mine*



Example of thickened tailings facility  
*Canadian Malartic mine*




Example of filtered tailings facility  
*Meliadine Mine*


## Types of TSFs and construction raises

TSFs are built for the management and storage of tailings. Often, they consist of a basin enclosed by dikes into which tailings are deposited. For practical and economic reasons, the dikes are typically raised incrementally to increase the capacity of the TSF during the life of the mine. Initially, a starter dike is constructed of borrow materials (such as soil, gravel, or sand) to contain the first few years of tailings production. Subsequent raises may be constructed of borrow material, rockfill or compacted tailings. In some cases, a completed open pit can be used to store tailings. The following four figures show some of the widely used construction methods for TSFs:


**Figure 2:** The **downstream method** involves constructing each raise on top of and downstream of the previous stage. The dike is founded entirely on natural soil. It is usually the method that requires the highest quantities of borrow material volume and space downstream.



**Figure 3:** The **upstream method** involves constructing each raise in the upstream direction such that they are partially supported on the tailings deposited after the previous raise. When properly designed, constructed, and operated, this methodology can be very safe. However, a robust understanding of the tailings' strength parameters is essential during the design phase of such facility.



**Figure 4:** The **centreline method** is a combination between the upstream and downstream methods. The raises are essentially constructed on top of one another without significant reliance on the tailings and limited encroachment on the downstream terrain.



**Figure 5:** The **in-pit method** consists of the use of an open pit to store tailings after mining activities have ceased. Once such facility is available, it becomes a tangible opportunity to use this capacity to store any type of tailings. It also provides advantages with respect to stability since it does not involve any retaining infrastructure such as a dam or a dike.



The stability of a TSF is dependent on many factors, such as geometric configuration, materials, construction method, seepage control, water management, internal erosion control, the characteristics of the retained tailings, foundation conditions, operation and maintenance.

The four methods shown here (upstream, downstream, centreline and in-pit) are basic concepts; in practice, there is a wide variety of geometries and techniques used in the design and construction of TSFs.

# Continuous Improvement Through Research and Innovation

Research on tailings is a major field of expertise that Agnico Eagle is developing in partnership with research institutions. The main projects support tailings management during operations and closure. A good understanding of the geotechnical and geochemical behaviour of tailing is important to ensure long-term stability of tailings management infrastructure.

Examples of our research and innovative work include the following projects initiated with the Research Institute on Mines and Environment (RIME) UQAT–Polytechnique:

- Behaviour of filtered tailings in northern conditions
- Development of an optimized approach to snow management on tailings storage facilities
- Optimization of rheological properties to minimize segregation of tailings during deposition
- Restoration of oxidized acid mine drainage generating tailings storage facilities
- Recovery of strategic metals and stabilization of contaminants
- Cement stabilization of acid-generating mine tailings
- Performance of geomembranes to control contamination

Symposium RIME (2022)



Experimental cells (RIME)

Agnico Eagle is actively present on many platforms to share new ideas and innovation with colleagues and researchers from the industry. We present and participate at many conferences to share new findings and improve our knowledge and practices.

**Table 1: Tailings Storage Facilities and Risk Evaluation Details****Meadowbank NUNAVUT, Canada****65°01'25"N 96°04'28"W (also manages tailings from Amaruq)**

Facility Name	Ownership	Accountable Executive Officer	Engineer of Record (note 1)	External Review Process (note 2)	Stored materials type	Status	Current Stored Volume (m³) (eo 2022)	Stored Volume (m³) in 5 years (eo 2027)	Closure plan and long-term monitoring (note 3)
North Cell TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Thomas Lepine	Yes, formalized, last review: summer 2022	Slurry Tailings	Active	14,400,000	Max = 14,400,000	Yes
South Cell TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Thomas Lepine	Yes, formalized, last review: summer 2022	Slurry Tailings	Active	10,800,000	Max = 10,800,000	Yes
Tailings InPit Disposal	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Thomas Lepine	Yes, formalized, last review: summer 2022	Slurry Tailings	Active	7,000,000	17,500,000	Yes

Facility Name	Infrastructure Name	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/Dike/ Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)
North Cell TSF	Saddle Dam 1	MBK-TSF-NSD1	Rockfill shell with liner tie-in key trench with transition	2009/2010	Downstream	N/A	15.0	2022 (Golder)	Yes	Both	Yes
	Saddle Dam 2	MBK-TSF-NSD2		2010			10.0				No
	Stormwater Dike	MBK-TSF-NSWD		2010			31.0				Yes
	NRF1	MBK-TSF-NRF1	Rockfill embankment with transition	2010	N/A		12.0				No
	NRF2	MBK-TSF-NRF2		2010			9.0				No
	North Cell Internal Structure	MBK-TSF- NIS		2018	Upstream		4.0				No
South Cell TSF	Saddle Dam 3	MBK-TSF-SSD3	Rockfill shell with liner tie-in key trench with transition	2016/2017	Downstream	N/A	10.0	2022 (Golder)	Yes	Both	No
	Saddle Dam 4	MBK-TSF-SSD4		2016/2017			8.0				No
	Saddle Dam 5	MBK-TSF-SSD5		2016/2017			10.0				No
	Central Dike	MBK-TSF-SCD		2012	2013-2018		49.0				Yes
Tailings InPit Disposal	Goose and Portage Pit	MBK-TSF-GIP	Tailings deposited in an open pit	2009-2019	N/A	N/A	N/A	N/A	Yes	Both	No

Facility Name	Infrastructure Name	Have stabilizing remedial actions been completed? (note 7)	Formal analysis of the downstream impacts (note 8)	Impact of climate change considered (note 9)	Potential Consequence Rating (note 10)	Guidelines applied (note 11)	Level of Practice Rating (note 12)	Factor of Safety (note 12)	Annual Probability of Failure (note 12)	Risk Rating (note 13)	Additional notes
North Cell TSF	Saddle Dam 1	Yes, 2012	Ongoing	Yes	Extreme	CDA	1.69	2.30	4.88E-08	Negligible	Note 14
	Saddle Dam 2	N/A					1.62	2.30	4.19E-08		
	Stormwater Dike	Yes, 2014			Minor		2.09	1.60	5.09E-05	Low	Note 15
	NRF1	Yes, 2013			Major		2.23	1.80	8.69E-06		Note 16
	NRF2	N/A					2.23	1.80	8.69E-06		
	North Cell Internal Structure						1.53	2.30	3.35E-08	Negligible	
South Cell TSF	Saddle Dam 3	N/A	Ongoing	Yes	Extreme	CDA	1.77	2.30	5.92E-08	Negligible	
	Saddle Dam 4				Major		1.68	2.30	4.79E-08		
	Saddle Dam 5						1.68	2.30	4.79E-08		
	Central Dike	Yes, 2015					1.93	2.00	9.96E-08		Note 17
Tailings InPit Disposal	Goose and Portage Pit	N/A	Ongoing	N/A	Major	N/A	1.09	2.80	1.24E-08	Negligible	

## Meliadine, NUNAVUT, Canada

63°02'07"N 92°13'11"W

Facility Name	Ownership	Accountable Executive Officer		Engineer of Record (note 1)	External Review Process (note 2)		Stored materials type	Status	Current Stored Volume (m³) (eo 2022)	Stored Volume (m³) in 5 years (eo 2027)	Closure plan and long-term monitoring (note 3)
Meliadine TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure		Thomas Lepine	Yes, formalized, last review: summer 2022		Filtered Tailings	Active	2,771,415	6,585,000	Yes
	Infrastructure Name	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/Dike/ Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)
	Filtered Tailings Facility	MEL-TSF-FS	Filtered tailings stack with erosion protection layer	2019	Lifts	N/A	33.0	2022 (Tetra Tec)	Yes	Both	No
	Infrastructure Name	Have stabilizing remedial actions been completed? (note 7)	Formal analysis of the downstream impacts (note 8)	Impact of climate change considered (note 9)	Potential Consequence Rating (note 10)	Guidelines applied (note 11)	Level of Practice Rating (note 12)	Factor of Safety (note 12)	Annual Probability of Failure (note 12)	Risk Rating (note 13)	Additional notes
	Filtered Tailings Facility	N/A	Ongoing	Yes	Major	CDA	1.64	1.90	1.38E-07	Negligible	

## Hope Bay, Nunavut, Canada

68°8'15"N 106°33'55"W

Facility Name	Ownership	Accountable Executive Officer		Engineer of Record (note 1)	External Review Process (note 2)		Stored materials type	Status	Current Stored Volume (m³) (eo 2022)	Stored Volume (m³) in 5 years (eo 2027)	Closure plan and long-term monitoring (note 3)
Tailings Impoundment Area (TIA)	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure		Thomas Lepine	Yes, formalized, last review: summer 2022		Slurry Tailings	Inactive (C&M)	1,380,000	1,380,000	Yes
	Infrastructure Name	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/Dike/ Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)
	North Dam	HPB-TSF-T-1	Rockfill shell with permafrost core and foundation with GCL and passive thermosyphon	2011-2012	N/A	N/A	9.5	2022 (SRK)	Yes	Both	No
	South Dam	HPB-TSF-T-2	Rockfill shell with GCL liner tie-in a permafrost key trench with transition	2018	Downstream	N/A	7.1	2022 (SRK)	Yes	Both	No
	Infrastructure Name	Have stabilizing remedial actions been completed? (note 7)	Formal analysis of the downstream impacts (note 8)	Impact of climate change considered (note 9)	Potential Consequence Rating (note 10)	Guidelines applied (note 11)	Level of Practice Rating (note 12)	Factor of Safety (note 12)	Annual Probability of Failure (note 12)	Risk Rating (note 13)	Additional notes
	North Dam	N/A	Completed	Yes	Extreme	CDA	1.51	1.50	2.60E-05	Medium	
	South Dam	N/A	Ongoing	Yes	Major	CDA	1.58	1.70	1.87E-06	Low	

## Goldex, Quebec, Canada

48°05'28"N 77°52'05"W

Facility Name	Ownership	Accountable Executive Officer		Engineer of Record (note 1)	External Review Process (note 2)		Stored materials type	Status	Current Stored Volume (m³) (eo 2022)	Stored Volume (m³) in 5 years (eo 2027)	Closure plan and long-term monitoring (note 3)
South TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure		Michael James	Yes, formalized, last review: 2022		Slurry Tailings	Active	3,880,124	7,000,000	Yes
	Infrastructure Name	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/Dike/ Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)
	Southwest Dike	GDX-TSF-SWD	Homogeneous till core	2008	N/A	N/A	5.0	2022 (SNC)	Yes	Both	No
	Internal Dike	GDX-TSF-IND					4.3				Yes
	Southeast Dike	GDX-TSF-SED					3.0				No
	Infrastructure Name	Have stabilizing remedial actions been completed? (note 7)	Formal analysis of the downstream impacts (note 8)	Impact of climate change considered (note 9)	Potential Consequence Rating (note 10)	Guidelines applied (note 11)	Level of Practice Rating (note 12)	Factor of Safety (note 12)	Annual Probability of Failure (note 12)	Risk Rating (note 13)	Additional notes
	Southwest Dike	N/A	Completed	Yes – in progress	Moderate	CDA	2.25	1.68	4.16E-05	Medium	Note 18
	Internal Dike	Yes, 2011			Minor		2.27	1.92	2.53E-06	Low	Note 19
	Southeast Dike	N/A			Moderate		2.40	1.79	2.68E-05	Medium	Note 20

## LaRonde, Quebec, Canada

48°14'52"N 78°26'09"W (also managing tailings of the former Lapa mine)

Facility Name	Ownership	Accountable Executive Officer	Engineer of Record (note 1)	External Review Process (note 2)	Stored materials type	Status	Current Stored Volume (m³) (eo 2022)	Stored Volume (m³) in 5 years (eo 2027)	Closure plan and long-term monitoring (note 3)
Principal TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Edouard Masengo	Yes, formalized, last review: 2022	Slurry Tailings	Active	32,650,000	Max = 32,650,000	Yes
Extension TSF A4	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Edouard Masengo	Yes, formalized, last review: 2022	Slurry Tailings	Active	3,400,000	Max = 3,400,000	Yes

Facility Name	Infrastructure Name	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/Dike/ Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)
Principal TSF	Dike 1	LAR-TSF-D1W	Rockfill with an upstream inclined till core and transition	1988	Centreline (2000 & 2002) and Upstream	2000, 2002, 2004, 2008, 2011, 2014, 2015, 2019 (2m each raise)	30.0	2022 (Golder)	Yes	Both	Yes
	Dike 2	LAR-TSF-D2		1988	Centreline		27.0				No
	Dike 7	LAR-TSF-D7E	Rockfill with central till core and transition	1998	Centreline (2000 & 2002) and Upstream after		23.0				No
Extension TSF A4	Dike 10	LAR-TSF-D10G	Rockfill with central till core and transition	2010	Not Raised	N/A	22.0	2022 (Golder)	Yes	Both	No

Facility Name	Infrastructure Name	Have stabilizing remedial actions been completed? (note 7)	Formal analysis of the downstream impacts (note 8)	Impact of climate change considered (note 9)	Potential Consequence Rating (note 10)	Guidelines applied (note 11)	Level of Practice Rating (note 12)	Factor of Safety (note 12)	Annual Probability of Failure (note 12)	Risk Rating (note 13)	Additional notes
Principal TSF	Dike 1	Yes, partially complete	Yes	Yes	Extreme	CDA	1.98	1.34	1.13E-03	High	Note 21
	Dike 2		N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Note 22
	Dike 7	N/A	Yes	Yes	Extreme	CDA	1.87	1.60	2.09E-05	Medium	Note 21
Extension TSF A4	Dike 10	N/A	Yes	Yes	Extreme	CDA	1.53	1.90	9.13E-08	Negligible	Note 23

# Canadian Malartic, Quebec, Canada

48°06'34"N 78°07'31"W

Facility Name	Ownership	Accountable Executive Officer		Engineer of Record (note 1)	External Review Process (note 2)	Stored materials type	Current Stored Volume (m³) (eo 2022)		Stored Volume (m³) in 5 years (eo 2027)		Closure plan and long-term monitoring (note 3)			
Canadian Malartic TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure		Edouard Masengo	Yes, formalized, Sept. 2022	Thickened Tailings	129,000,000		Max = 152,500,000		Yes			
	Infrastructure Name	Status	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/ Dike/Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)		
	Starter Berm West	Active	MCM-TSF-BDDW	Permeable homogeneous rockfill with upstream transition	2011-2012	Upstream	Max of 3 raises of 2m each per year	40.0	2022 (WSP-Golder)	Yes	Both	No		
	Starter Berm South		MCM-TSF-BDDS		2011-2012			36.0						
	Dike 5		MCM-TSF-MD5	Homogeneous till core with sand drain and rock berm	1991-1992			40.0				Yes		
	Starter Berm Central		MCM-TSF-BDDC	Permeable homogeneous rockfill with upstream transition	2011-2012			40.0						
	Dike C		MCM-TSF-MDC	Rockfill with till core and transition	2010	Downstream		24.0				No		
	Dike PR5		MCM-TSF-PR5	Permeable homogeneous rockfill with upstream transition	2017-2019	Upstream		36.0						
	Dike PR6		MCM-TSF-PR6		2021-2022	N/A	N/A	20.0						
	Dike PR7		MCM-TSF-PR7		2022 (in constr.)			24.0						
	Starter Berm East		MCM-TSF-BDDE		2011-2012	Upstream		30.0						
	Dike North	MCM-TSF-DN	Starter berm: rockfill with upstream clay core and transition	1960-1970	20.0			N/A						
	Dike South	MCM-TSF-DS	Starter berm: rockfill with clay core and transition	1960-1970	23.5									
	Infrastructure Name	Have stabilizing remedial actions been completed? (note 7)	Formal analysis of the downstream impacts (note 8)	Impact of climate change considered (note 9)	Potential Consequence Rating (note 10)	Guidelines applied (note 11)	Level of Practice Rating (note 12)	Factor of Safety (note 12)	Annual Probability of Failure (note 12)	Risk Rating (note 13)	Additional notes			
	Starter Berm West	2020	Ongoing	Yes	Extreme	CDA	1.78	1.50	6.30E-05	Medium	Note 24			
	Starter Berm South	N/A					1.80	2.70	6.31E-08	Negligible				
	Dike 5	Yes, March 2021					Completed	1.96	1.60	2.83E-05	Medium		Note 25	
	Starter Berm Central	N/A	Ongoing				Yes	1.80	2.60	6.31E-08	Negligible		Note 26	
	Dike C												Completed	1.80
	Dike PR5		Ongoing				1.93	1.50	1.06E-04	Medium				
	Dike PR6		Ongoing				1.31	2.90	2.05E-08	Negligible				
	Dike PR7		No				1.04	1.50	5.50E-06	Low	Note 28			
	Starter Berm East		Ongoing		Moderate		1.78	1.40	2.57E-04	Medium	Note 29			
	Dike North		N/A		N/A	N/A	N/A	N/A	N/A	N/A	Note 30			
	Dike South										Note 31			

## Macassa, Ontario, Canada

48°08'15"N 80°04'15"W

Facility Name	Ownership	Accountable Executive Officer		Engineer of Record (note 1)	External Review Process (note 2)	Stored materials type	Current Stored Volume (m³) (eo 2022)	Stored Volume (m³) in 5 years (eo 2027)		Closure plan and long-term monitoring (note 3)		
Macassa TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure		Michael James	Yes, via DSR 2016-19	Slurry Tailings	~53 ha	~53 ha		Yes		
North TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure		Michael James	Yes, via DSR 2016-19	Thickened Tailings	656,500	Max = 3,700,000		Yes		

Facility Name	Infrastructure Name	Status	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/ Dike/Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)
Macassa TSF	Upper Dam B Dike B	Inactive	MCS-TSF-UBB	Rockfill starter dam on tailings, raised using rockfill on tailings beaches	Circa 1933	Upstream	2018/2019	23.0	2022 (EXP)	Yes	Both	Yes
	Lower Dam B Dike B		MCS-TSF-LBB					21.0				
	Dam G		MCS-TSF-DMG	Homogeneous clay core starter dam, raised with tailings	Circa 1933			10.0				
	Dam F		MCS-TSF-DMF	Homogeneous till fill core starter dam, raised with tailings				12.0				
	Dam F Ext.		MCS-TSF-DEF	Constructed from tailings	Unknown			2.0				
	Dam E		MCS-TSF-DME					9.0				
	Lower Dam E		MCS-TSF-DLE					18.0				
North TSF	Dam 1	Active	MCS-TSF-DM1B	Rockfill with upstream geo-membrane	2018	Centreline	N/A	16.0	2022 (EXP)	Yes	Both	No
	Dam 2A		MCS-TSF-D2A					7.0				
	Dam 2D		MCS-TSF-D2D					17.0				
	Dam 2E		MCS-TSF-D2E					4.0				
	Dam 3		MCS-TSF-DM3					14.0				
	Dam 4		MCS-TSF-DM4					4.0				

Macassa, Ontario, Canada *(continued)*

48°08'15"N 80°04'15"W

Facility Name	Infrastructure Name	Have stabilizing remedial actions been completed? (note 7)	Formal analysis of the downstream impacts (note 8)	Impact of climate change considered (note 9)	Potential Consequence Rating (note 10)	Guidelines applied (note 11)	Level of Practice Rating (note 12)	Factor of Safety (note 12)	Annual Probability of Failure (note 12)	Risk Rating (note 13)	Additional notes
Macassa TSF	Upper Dam B Dike B	Yes, 2019	Yes	Yes	Major	CDA	2.71	1.50	2.70E-03	High	Note 32
	Lower Dam B Dike B						2.71	1.80	1.66E-04	High	
	Dam G						2.71	1.70	4.20E-04	High	
	Dam F						2.71	1.80	1.66E-04	High	
	Dam F Ext.						2.71	2.00	2.58E-05	Medium	
	Dam E						2.71	1.70	4.20E-04	High	
	Lower Dam E						2.71	1.90	6.53E-05	Medium	
North TSF	Dam 1	N/A	Yes	Yes	Extreme	CDA	1.82	1.62	1.35E-05	Medium	
	Dam 2A				Moderate		1.82	2.20	6.64E-08	Negligible	
	Dam 2D				Extreme		1.82	1.63	1.18E-05	Medium	
	Dam 2E				Moderate		1.82	2.20	6.64E-08	Negligible	
	Dam 3				Minor		1.82	2.20	6.64E-08	Negligible	
	Dam 4				Negligible		1.82	2.20	6.64E-08	Negligible	

## Holt Complex, Ontario, Canada

48°29'18"N 79°43'48"W

Facility Name	Ownership	Accountable Executive Officer	Engineer of Record (note 1)	External Review Process (note 2)	Stored materials type	Current Stored Volume (m³) (eo 2020)	Stored Volume (m³) in 5 years (eo 2027)	Closure plan and long-term monitoring (note 3)
North Basin TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Michael James	Yes, via DSR 2017-19	Slurry Tailings	6,500,000 (total of combined basins)	Max = 8,000,000 (total of combined basins)	Yes
Southwest Basin TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Michael James	Yes, via DSR 2017-19	Slurry Tailings	6,500,000 (total of combined basins)	Max = 8,000,000 (total of combined basins)	Yes

Facility Name	Infrastructure Name	Status	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/Dike/Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)
North Basin TSF	Dam 1	Inactive – Care & Maintenance	HLT-TSF-NB1	Clay Core (original) and till core (raises); d/s granular filter, finger drain and shell, u/s till shell and toe berm (original); u/s granular shell (raises); cobbles erosion protection	1988	Centreline, upstream, downstream	1995 c/l, 2011 u/s, 2020 d/s	14.0	2022 (EXP)	Yes	Both	Yes
	Dam 2		HLT-TSF-NB2					19.0				
	Dam 3		HLT-TSF-NB3					11.7				
	Dam 3A		HLT-TSF-NB3A					13.7				
	Dam 4		HLT-TSF-NB4					11.6				
	Dam 5		HLT-TSF-NB5	Mainly cobble raises d/s over tailings and buttressed with tailings	14.2							
	Dam 4A		HLT-TSF-NB4A	Till core with key trench; u/s and d/s granular shell and cobbles/rock erosion protection	1995	Upstream, downstream	2011 u/s, 2020 d/s	5.6				
	Dam 7		HLT-TSF-NB7	Clay core with key trench, granular shell above core, u/s, and d/s cobble erosion protection				7.0				
	Dam 8 North		HLT-TSF-NB8N					7.0				
	Dam 8 South		HLT-TSF-NB8S					7.0				
	Dam 14		HLT-TSF-NB14	Zoned earthfill/rockfill structures with geomembrane liners	2021	N/A	N/A	~2.0				No

# Holt Complex, Ontario, Canada (continued)

48°29'18"N 79°43'48"W

Facility Name	Infrastructure Name	Status	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/Dike/Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)
Southwest Basin TSF	Dam 6	Inactive – Care & Maintenance	HLT-TSF-SWB6	Till core with key trench (original), clay core (raises); granular filters, shells & erosion protection on u/s and d/s. Toe drain at d/s western half of dam	1988	Centreline, upstream, downstream	1995 c/l, 2012 & 2017 u/s, 2020 d/s	12.2	2022 (EXP)	Yes	Both	Yes
	Dam 10		HLT-TSF-SWB10	Pit run granular shell and d/s and u/s toe berms with surface erosion protection	1997-1998	Centreline, upstream, downstream	2000 c/l, 2013 c/l, 2017 u/s, 2020 d/s	11.0				
	Dam 6 Wing		HLT-TSF-SWB6W	Clay core with key trench, granular shell, u/s riprap bedding, D/s cobble erosion protection	2001	Upstream, downstream	2017 u/s, 2020 d/s	2.0		Yes	Both	No
	Dam 15A		HLT-TSF-SWB15A	Zoned earthfill/rockfill structures with geomembrane liners	2021	N/A	N/A	~5.0				
	Dam 15B		HLT-TSF-SWB15B					~2.0				
Facility Name	Infrastructure Name	Have stabilizing remedial actions been completed? (note 7)	Formal analysis of the downstream impacts (note 8)	Impact of climate change considered (note 9)	Potential Consequence Rating (note 10)	Guidelines applied (note 11)	Level of Practice Rating (note 12)	Factor of Safety (note 12)	Annual Probability of Failure (note 12)	Risk Rating (note 13)	Additional notes	
North Basin TSF	Dam 1	Yes, 2020-2021	Yes	Yes	Low	CDA		1.50			Note 33	
	Dam 2							1.70				
	Dam 3							1.50				
	Dam 3A							1.70				
	Dam 4							1.50				
	Dam 5							N/A				
	Dam 4A							1.70				
	Dam 7							1.50				
	Dam 8 North							1.70				
	Dam 8 South							1.50				
	Dam 14	N/A						2.00				
Southwest Basin TSF	Dam 6	Yes, 2020-2021	Yes	Yes	Moderate	CDA					Note 33	
	Dam 10				Moderate							
	Dam 6 Wing				Low							
	Dam 15A	Low			2.50							
	Dam 15B	Low			1.60							

# Detour Lake, Ontario, Canada

50°02'46"N 79°41'02"W

Facility Name	Ownership	Accountable Executive Officer		Engineer of Record (note 1)	External Review Process (note 2)	Stored materials type	Current Stored Volume (m³) (eo 2022)		Stored Volume (m³) in 5 years (eo 2027)		Closure plan and long-term monitoring (note 3)	
Cell 1	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure		Mathi Shan (WSP)	Yes, 2023	Slurry Tailings	235,500,000		Max = 235,500,000		Yes	
Cell 2	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure		Simon Dickinson (BGC)	Yes, 2023	Slurry Tailings	29,600,000		140,700,000		Yes	
Facility Name	Infrastructure Name	Status	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/Dike/Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)
Cell 1	Section B1	Inactive	DLM-TSF-C1-02	Centreline raised, glacial till core dam, with downstream filters.	2011	Centreline	Annual to 2020	52.0	2022 (WSP)	Yes	External only	No
	Section C1		DLM-TSF-C1-03					54.0				
	Section C3		DLM-TSF-C1-04					51.0				
Cell 2	East Dam	Active	DLM-TSF-C2-03	Till core with graded d/s filters and rockfill shells, d/s raises – rockfill & composite geo-membrane/compacted till liner	2018	Down stream	Annual to 2022	31.0	2022 (BGC)	Yes	External only	No
	South Dam		DLM-TSF-C2-04					17.0		Yes	External only	
Facility Name	Infrastructure Name	Have stabilizing remedial actions been completed? (note 7)	Formal analysis of the downstream impacts (note 8)	Impact of climate change considered (note 9)	Potential Consequence Rating (note 10)	Guidelines applied (note 11)	Level of Practice Rating (note 12)	Factor of Safety (note 12)	Annual Probability of Failure (note 12)	Risk Rating (note 13)	Additional notes	
Cell 1	Section B1	N/A	Yes	No	Extreme	CDA / Ministry of Natural Resources, Lakes and Rivers Improvement Act (LIRA) Technical Bulletins	1.94	1.60	2.64E-05	Medium		
	Section C1						1.94	1.60	2.64E-05	Medium		
	Section C3						1.94	1.90	4.05E-07	Negligible		
Cell 2	East Dam	N/A	No	No	Extreme	CDA	1.38	1.70	9.29E-07	Negligible		
	South Dam						1.38	2.80	2.40E-08	Negligible		

## Kittila, Finland

67°54'52"N 25°24'20"E

Facility Name	Ownership	Accountable Executive Officer	Engineer of Record (note 1)	External Review Process (note 2)	Stored materials type	Status	Current Stored Volume (m³) (eo 2022)	Stored Volume (m³) in 5 years (eo 2027)	Closure plan and long-term monitoring (note 3)
CIL1 TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Edouard Masengo	Yes, formalized, 2022	Slurry Tailings	Inactive	300,000	Max = 300,000	Yes
CIL 2 TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Edouard Masengo	Yes, formalized, 2022	Slurry Tailings	Active	3,800,000	Max = 5,100,000	Yes
NP3 TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Edouard Masengo	Yes, formalized, 2022	Slurry Tailings	Active	8,800,000	Max = 8,800,000	Yes
NP4 TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Edouard Masengo	Yes, formalized, 2022	Slurry Tailings	Active	1,800,000	Max = 7,500,000	Yes

Facility Name	Infrastructure Name	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/Dike/ Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)
CIL1 TSF	CIL1 Dam	KIT-TSF-CIL1	Rockfill with u/s inclined moraine core, transition & bituminous geomembrane	2007-2008	N/A	N/A	15.0	2022 (WSP)	Yes	Both	No
CIL 2 TSF	CIL2 South Dam - CIL2/CIL1 Divider	KIT-TSF-CIL2S	As above with additional d/s inclined moraine core	2007-2008	Upstream	N/A	19.0	2022 (WSP)	Yes	Both	No
	CIL2 West	KIT-TSF-CILW	As with CIL1				19.0				
NP3 TSF	NP3 North Dam	KIT-TSF-NP3N	As with CIL1	2010-2011	Upstream	N/A	28.5	2022 (WSP)	Yes	Both	No
	NP3 West Dam	KIT-TSF-NP3W					28.5		Yes	Both	Yes
	NP3 South Dam - NP3/CIL2 Divider	KIT-TSF-NP3S	As with CIL2S				28.5		Yes	Both	No
NP4 TSF	NP4 Dam	KIT-TSF-NP4	As with CIL1	2019-2020	N/A	N/A	15.0	2022 (WSP)	Yes	Both	No

Facility Name	Infrastructure Name	Have stabilizing remedial actions been completed? (note 7)	Formal analysis of the downstream impacts (note 8)	Impact of climate change considered (note 9)	Potential Consequence Rating (note 10)	Guidelines applied (note 11)	Level of Practice Rating (note 12)	Factor of Safety (note 12)	Annual Probability of Failure (note 12)	Risk Rating (note 13)	Additional notes
CIL1 TSF	CIL1 Dam	N/A	Ongoing	Yes – in progress	Extreme	Finnish Reg's/ CDA	1.91	1.86	6.46E-07	Negligible	
CIL 2 TSF	CIL2 South Dam - CIL2/CIL1 Divider	N/A	Ongoing	Yes – in progress	Extreme	Finnish Reg's/ CDA	1.76	1.81	7.40E-07	Negligible	
	CIL2 West						1.76	1.77	1.30E-06	Low	
NP3 TSF	NP3 North Dam	N/A	Ongoing	Yes – in progress	Extreme	Finnish Reg's/ CDA	1.64	2.09	4.41E-08	Negligible	Note 34
	NP3 West Dam	Yes, 2015					1.64	2.03	4.41E-08		
	NP3 South Dam – NP3/CIL2 Divider	N/A					1.67	1.84	3.50E-07		
NP4 TSF	NP4 Dam	N/A	Ongoing	Yes – in progress	Extreme	Finnish Reg's/ CDA	1.13	1.70	3.92E-07	Negligible	

## Fosterville, Australia

36°41'30"S 144°30'00E

Facility Name	Ownership	Accountable Executive Officer	Engineer of Record (note 1)	External Review Process (note 2)	Stored materials type	Status	Current Stored Volume (m³) (eo 2022)	Stored Volume (m³) in 5 years (eo 2027)	Closure plan and long-term monitoring (note 3)
<b>TSF 1</b>	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Robert Grant	Yes, formalized, 2022	Slurry Tailings	Inactive	4,600,000	Max = 5,900,000	Yes
<b>Inpit-TSF 2</b>	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Robert Grant	Yes, formalized, 2022	Slurry Tailings	Active	1,698,000	Max = 1,698,000	Yes
<b>Inpit-TSF 3</b>	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Robert Grant	Yes, formalized, 2022	Slurry Tailings	Active	533,333	Max = 533,333	Yes
<b>TSF 4</b>	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Robert Grant	Yes, formalized, 2022	Slurry Tailings	Active	2,340,000	Max = 3,700,000	Yes
<b>CIL-HS</b>	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Robert Grant	Yes, formalized, 2022	Dried Tailings	Active	567,652	Max = 760,562	Yes
<b>CIL-TSF 1</b>	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Robert Grant	Yes, formalized, 2022	Slurry Tailings	Active	22,727	Max = 54,545	Yes
<b>CIL-TSF 2</b>	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Robert Grant	Yes, formalized, 2022	Slurry Tailings	Active	3,800	Max = 54,545	Yes
<b>CIL-TSF 3</b>	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	Robert Grant	Yes, formalized, 2022	Slurry Tailings	Inactive	78,300	Max = 78,300	Yes

Facility Name	Infrastructure Name	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/Dike/ Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)
<b>TSF 1</b>	TSF 1	FSV-TSF-1-S1SE	Clay lined earth embankment facility, with under-drainage and central gravity decant system	2004-2005	Centreline, upstream	2006, 2008-2010, 2012-2013, 2018, 2023	25.5	2022 (Advisian)	Yes	Both	No
<b>Inpit-TSF 2</b>	Inpit-TSF 2	FSV-TSF-2-S1	In-pit tailings storage facility, with under-drainage	2010	N/A	N/A	N/A	2022 (Advisian)	Yes	Both	No
<b>Inpit-TSF 3</b>	Inpit-TSF 3	FSV-TSF-3-S1	In-Pit storage facility, with under-drainage and clay liner on the upper 21 m of the southern side of the pit	2013	N/A	N/A	N/A	2022 (Advisian)	Yes	Both	No
<b>TSF 4</b>	TSF 4	FSV-TSF-4-S1SE	Clay lined earth embankment facility, with under-drainage and central gravity decant system	2015	Downstream	2020	21.3	2022 (Advisian)	Yes	Both	No
<b>CIL-HS</b>	CIL-HS	FSV-TSF-CIL-HS1-S4	HDPE, Clay & GCL lined pads to store partially drained, mechanically placed CIL Tailings, with drains	2011	N/A	HS1 – 2011 HS2 – 2013 HS3 – 2020 HS4 - 2023	16.0	2022 (Advisian)	Yes	Both	No
<b>CIL-TSF 1</b>	CIL-TSF 1	FSV-TSF-CIL1-S2	Dam created by cut to fill within HLF, underlain by HDPE & subdrains	2005	N/A	N/A	17.0	2022 (Advisian)	Yes	Both	No
<b>CIL-TSF 2</b>	CIL-TSF 2	FSV-TSF-CIL2-S1	Dam created by cut to fill within HLF, underlain by HDPE & subdrains	2006	N/A	N/A	15.0	2022 (Advisian)	Yes	Both	No
<b>CIL-TSF 3</b>	CIL-TSF 3	FSV-TSF-CIL3-S1	Dam created by cut to fill within HLF, underlain by HDPE & subdrains	2007	N/A	N/A	15.0	2022 (Advisian)	Yes	Both	No

**Fosterville, Australia** *(continued)***36°41'30"S 144°30'00E**

Facility Name	Infrastructure Name	Have stabilizing remedial actions been completed? (note 7)	Formal analysis of the downstream impacts (note 8)	Impact of climate change considered (note 9)	Potential Consequence Rating (note 10)	Guidelines applied (note 11)	Level of Practice Rating (note 12)	Factor of Safety (note 12)	Annual Probability of Failure (note 12)	Risk Rating (note 13)	Additional notes
<b>TSF 1</b>	TSF 1	N/A	Yes	No	High A	ANCOLD 2019	1.53	1.50	2.79E-05	Medium	
<b>Inpit-TSF 2</b>	Inpit-TSF 2	N/A	Yes	No	Very Low	ANCOLD 2019	2.81	2.80	4.19E-06	Negligible	
<b>Inpit-TSF 3</b>	Inpit-TSF 3	N/A	Yes	No	Very Low	ANCOLD 2019	2.78	2.00	4.30E-05	Low	
<b>TSF 4</b>	TSF 4	N/A	Yes	No	High A	ANCOLD 2019	1.44	1.80	2.73E-07	Negligible	
<b>CIL-HS</b>	CIL-HS	N/A	Yes	No	High C	ANCOLD 2019	2.11	1.60	5.64E-05	Medium	Note 35
<b>CIL-TSF 1</b>	CIL-TSF 1	N/A	Yes	No	High C	ANCOLD 2019	2.51	2.29	1.05E-06	Low	
<b>CIL-TSF 2</b>	CIL-TSF 2	N/A	Yes	No	High C	ANCOLD 2019	2.13	2.23	1.85E-07	Negligible	
<b>CIL-TSF 3</b>	CIL-TSF 3	N/A	Yes	No	High C	ANCOLD 2019	2.20	2.41	2.51E-07	Negligible	

## Pinos Altos, Chihuahua, Mexico

28°16'13"N 108°17'58"W

Facility Name	Ownership	Accountable Executive Officer		Engineer of Record (note 1)	External Review Process (note 2)	Stored materials type	Status	Current Stored Volume (m³) (eo 2022)	Stored Volume (m³) in 5 years (eo 2027)	Closure plan and long-term monitoring (note 3)
Pinos Altos TMF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure		Michael James	Yes, formalized, 2022	Filtered Tailings	Inactive	5,152,000	5,152,000	Yes
Oberon de Weber In-Pit TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure		Michael James	Yes, formalized, 2022	Filtered Tailings	Active	5,300,000	5,500,000	Yes
Facility Name	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/Dike/Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)
Pinos Altos TMF	PIN-TSF-OLD	Filtered tailings stack with erosion protection layer	2008	Filter Stack	N/A	105.0	2022 (EOR)	Yes	Both	Yes
Oberon de Weber In-Pit TSF	PIN-TSF-OWIP	Filtered tailings disposal in an open pit	2015	Filter Stack	N/A	N/A	2022 (EOR)	Yes	Both	No
Facility Name	Have stabilizing remedial actions been completed? (note 7)	Formal analysis of the downstream impacts (note 8)	Impact of climate change considered (note 9)	Potential Consequence Rating (note 10)	Guidelines applied (note 11)	Level of Practice Rating (note 12)	Factor of Safety (note 12)	Annual Probability of Failure (note 12)	Risk Rating (note 13)	Additional notes
Pinos Altos TMF	Yes, 2011	Pending	Yes – in progress	Minor	CDA	1.75	1.75	1.67E-06	Low	Note 36
Oberon de Weber In-Pit TSF	N/A	N/A	N/A	Negligible	N/A	1.18	2.80	1.50E-08	Negligible	Note 37

## Closed & Legacy Sites

### Quebec, Canada

Facility Name	Ownership	Accountable Executive Officer	Engineer of Record (note 1)	External Review Process (note 2)	Stored materials type	Status	Current Stored Volume (m³) (eo 2022)	Stored Volume (m³) in 5 years (eo 2027)	Closure plan and long-term monitoring (note 3)
Joutel TMF North	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	No official EOR	No	Slurry Tailings	Inactive	4,500,000	Max = 4,500,000	Yes
Joutel TMF South	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	No official EOR	No	Slurry Tailings	Inactive	2,200,000	Max = 3,300,000	Yes
Camflo TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	No official EOR	No	Slurry Tailings	Inactive – C&M	P1=53 ha P2=25 ha P3=23 ha	P1=53 ha P2=25 ha P3=23 ha	Yes
Les Terrains Aurifères	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	No official EOR	No	Slurry Tailings	Inactive – Decomm'd	TSF=60 ha Sed pond= 28 ha Pol pond=16 ha	TSF=60 ha Sed pond= 28 ha Pol pond= 16 ha	Yes

Facility Name	Infrastructure Name	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/Dike/ Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)
Joutel TMF North	TMF North Dike	JTL-TSF-JND	Rockfill with an upstream inclined till core and transition	1974-1975	Downstream	1975-1986	9.0	2021 (SNC)	Yes	Both	Yes
Joutel TMF South	TMF East Dike	JTL-TSF-JSE	Rockfill dam	1986-1987	Downstream	1987-1991	6.0	2021 (SNC)	Yes	Both	Yes
	TMF South Dike	JTL-TSF-JSS	Rockfill with u/s inclined till core & transition; portions with central clay core				6.0				
Camflo TSF	Dam 1		Constructed with tailings	1969	Upstream	1983-2016	~9.5	2022 (WSP)	Yes	Both	Yes
	Dam 2		Constructed with tailings and rockfill berm	1989		2002-2017	~14.5				
	Dam 3			1989		2003, 2017	~13				
Les Terrains Aurifères	LTA		Constructed with tailings	1977	Upstream	1977-1994	~15	2022 (A-M Dagenais)	No	Both	No

Facility Name	Infrastructure Name	Have stabilizing remedial actions been completed? (note 7)	Formal analysis of the downstream impacts (note 8)	Impact of climate change considered (note 9)	Potential Consequence Rating (note 10)	Guidelines applied (note 11)	Level of Practice Rating (note 12)	Factor of Safety (note 12)	Annual Probability of Failure (note 12)	Risk Rating (note 13)	Additional notes
Joutel TMF North	TMF North Dike	Yes	Ongoing	Yes – in progress	Major	CDA	2.37	1.57	2.82E-04	High	Note 38
Joutel TMF South	TMF East Dike	Yes	Ongoing	Yes – in progress	Major	CDA	2.28	2.80	3.62E-07	Negligible	Note 39
	TMF South Dike						2.39	1.40	2.12E-03	High	Note 40
Camflo TSF	Dam 1	No	No	Yes		CDA		1.50			Note 41
	Dam 2	No	No	Yes		CDA		1.50			
	Dam 3	No	No	Yes		CDA		1.50			
Les Terrains Aurifères	LTA	No	No	No							

AGNICO EAGLE 2023 TAILINGS SUMMARY REPORT

Ontario, Canada

Facility Name	Ownership	Accountable Executive Officer	Engineer of Record (note 1)	External Review Process (note 2)	Stored materials type	Status	Current Stored Volume (m³) (eo 2022)	Stored Volume (m³) in 5 years (eo 2027)	Closure plan and long-term monitoring (note 3)
Cobalt Nova Scotia Tailings Area	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	No official EOR	No	Slurry Tailings	Inactive	4.78 ha	4.78 ha	Yes
Kirkland Minerals TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	No official EOR	No	Slurry Tailings	Inactive	~18 ha, ~2,094,025	~18 ha, ~2,094,025	No plan, Yes monitoring
Aquarius Tailings Areas	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	No official EOR	No	Slurry Tailings	Inactive	~10 ha, 350,000 tonnes	~10 ha, 350,000 tonnes	Yes
Upper Canada No.1 Tailings Area	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	No official EOR	No	Slurry Tailings	Inactive	unknown	unknown	Yes
Bidgood TSF	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	No official EOR	No	Slurry Tailings	Inactive – Decomm'd	~11.2 ha, 600,000 tonnes	~11.2 ha, 600,000 tonnes	No plan, Yes monitoring

Facility Name	Infrastructure Name	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/Dike/ Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)
Cobalt Nova Scotia Tailings Area	Nova Scotia Retaining Berm	COB-TSF-COB	Rockfill with foundation filter	1992, 2001	N/A	N/A	9.0	2018 (Golder)	No	Both	Yes
Kirkland Minerals TSF	North Dike	KLM-TSF-ND1	Constructed with tailings	Unknown	Upstream	Unknown	~10.0	2022 (WSP)	No	Both	Yes
	East Dike	KLM-TSF-ED1	Constructed with tailings	Unknown	Upstream	Unknown	~10.0	2022 (WSP)	No	Both	Yes
Aquarius Tailings Areas	Tailings Area #1		Multiple celled 5ha impoundment, west of the mine/mill site	1983	Centreline	N/A	~11.0	2022 (EXP)	Yes	Both	No
	Tailings Area #2		Similar sized impoundment, northeast of the mine/mill site	1986	Centreline	N/A	~11.0	2022 (EXP)	Yes	Both	No
Upper Canada No.1 Tailings Area	No.1 Tailings Dam	UC-TSF-N1	Rockfill shell dam with sand gravel filter; may also include tailings	Unknown		Unknown	~7.0	2022	Yes	Both	Unknown
Bidgood Tailings Area	Bidgood South Dam		Downstream dam; probably rock fill	Unknown	N/A	N/A	~6.0	2022	No	Both	Unknown

Facility Name	Infrastructure Name	Have stabilizing remedial actions been completed? (note 7)	Formal analysis of the downstream impacts (note 8)	Impact of climate change considered (note 9)	Potential Consequence Rating (note 10)	Guidelines applied (note 11)	Level of Practice Rating (note 12)	Factor of Safety (note 12)	Annual Probability of Failure (note 12)	Risk Rating (note 13)	Additional notes
Cobalt Nova Scotia Tailings Area	Nova Scotia Retaining Berm	Yes, 2001	Ongoing	Yes – in progress	Minor to Moderate	N/A					Note 42
Kirkland Minerals TSF	North Dike	Pending	Yes	Pending	Moderate	CDA		1.60		High (estimated)	Note 43
	East Dike	Pending	Yes	Pending	Major	CDA		1.20		High (estimated)	
Aquarius Tailings Areas	Tailings Area #1	N/A	No	No		N/A					
	Tailings Area #2	N/A	No	No		N/A					
Upper Canada No.1 Tailings Area	No.1 Tailings Dam	N/A	Yes	Yes	Moderate	CDA	2.71	1.59	1.16E-03	High	Note 44
Bidgood Tailings Area	Bidgood South Dam	No	No	No	N/A	N/A					Note 45

## Northern Territory, Australia

Facility Name	Ownership	Accountable Executive Officer	Engineer of Record (note 1)	External Review Process (note 2)	Stored materials type	Status	Current Stored Volume (m³) (eo 2022)	Stored Volume (m³) in 5 years (eo 2027)	Closure plan and long-term monitoring (note 3)
<b>Cosmo Howley TSF</b>	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	No official EOR	Yes, formalized, 2022	Slurry Tailings	Inactive - closed	Unknown	Unknown	In progress
<b>Union Reef TSF</b>	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	No official EOR	Yes, formalized, 2022	Slurry Tailings	Inactive – C&M	Unknown	Unknown	No plan, Yes monitoring
<b>Pine Creek TSF</b>	Agnico Eagle Mines Ltd.	Michel Julien, VP Environment & Critical Infrastructure	No official EOR	Yes, formalized, 2022	Slurry Tailings	Inactive – closed & capped	Unknown	Unknown	No plan, Yes monitoring

Facility Name	Infrastructure Name	Unique Identifier	Construction Type	Year(s) of Construction (starter)	Type of Raise (if applicable)	Year(s) of Raises	Current Max Dam/Dike/ Pile Height (m)	Latest External Inspection (note 4)	Relevant engineering records (note 5)	Internal and external engineering oversight and support (note 6)	Has this infrastructure, at any point in its life, experienced notable stability concerns? (note 7)
<b>Cosmo Howley TSF</b>	Embankment		Centreline, upper slope, intermediate bench, and lower slope w/ NE spillway	Unknown	N/A	N/A	22.5	2022 (KCB)	Yes	Both	Yes
<b>Union Reef TSF</b>	North, West & South Embankments		Centreline, with edge rock berm around TSF capping, spillway on eastern abutment south dam	Unknown	N/A	N/A	18.0	2022 (KCB)	Yes	Both	Yes
<b>Pine Creek TSF</b>	Main Cell - East & South Embankments		Centreline via thin lifts, mechanical compaction	Unknown	N/A	N/A	34.4	2022 (KCB)	Yes	Both	Yes
	North-west Cell		Valley fill contained by the main cell, no dividing embankment between cells visible				34.4		Yes	Both	Yes
	Upper Cell – East, South & West Embankments		Embankments via waste dumped in ~5m thick lifts without mechanical compaction				34.4		Yes	Both	Yes

Facility Name	Infrastructure Name	Have stabilizing remedial actions been completed? (note 7)	Formal analysis of the downstream impacts (note 8)	Impact of climate change considered (note 9)	Potential Consequence Rating (note 10)	Guidelines applied (note 11)	Level of Practice Rating (note 12)	Factor of Safety (note 12)	Annual Probability of Failure (note 12)	Risk Rating (note 13)	Additional notes
<b>Cosmo Howley TSF</b>	Embankment	Yes	Yes	Yes – in progress	Significant	ANCOLD 2019					Note 46
<b>Union Reef TSF</b>	North, West & South Embankments	Yes, 2022-2023	Yes, simplified	Yes – in progress	High C	ANCOLD 2019					Note 47
<b>Pine Creek TSF</b>	Main Cell - East & South Embankments	In progress	Yes	Yes – in progress	High A	ANCOLD 2019					Note 48
	North-west Cell	In progress									
	Upper Cell – East, South & West Embankments	In progress									

## Disclosure Clarification Notes:

- Note 1:** As part of our governance with tailings management, Engineers of Record have been appointed to our operating sites.
- Note 2:** External review process is formalized and refers to either an external review board or a formal external review.
- Note 3:** Closure plans are updated periodically and include a long-term monitoring program.
- Note 4:** Date and consultant that carried out last external inspection.
- Note 5:** Refers to available documents like investigation, design, analysis, and as-built documents to support any future review. The quality and breadth of the available documentation were assessed as part of the risk evaluation to determine the annual probability of failure.
- Note 6:** Expert staff have been added to support sites in collaboration with external consultants.
- Note 7:** If remedial actions ever had to be taken (during any part of its life) because the infrastructure failed to be confirmed as stable or experienced notable stability issues (i.e., Answer is Yes), see the "Additional Notes" section below for the respective details of each infrastructure.
- Note 8:** Analysis of downstream impacts are being reviewed on an ongoing basis.
- Note 9:** A Climate Change Action Plan is being developed and will be integrated in updated closure plans. Currently several sites include effects of climate change, but practice is not consistent.
- Note 10:** The consequence rating is included here. Details of potential consequences associated with a loss of tailings containment for each consequence rating are presented in Appendix C, Tables A through C.
- Note 11:** CDA refers to Canadian Dam Association, and ANCOLD refers to Australian National Committee on Large Dams. Both are the members of the International Commission on Large Dams.
- Note 12:** The scores of Level of Practice, Factor of Safety and Annual Probability of Failure were all determined and used in the determination of the risk rating for each infrastructure. Details for the evaluation are described in the Appendix C Risk Evaluation Methodology.
- Note 13:** The risk rating is a product of the consequence rating and the probability of failure rating. This is further described in the Appendix C Risk Evaluation Methodology.

## Additional Notes:

### MEADOWBANK

- Note 14:** Saddle Dam 1 – Freezing of the dam slower than expected after construction, successfully mitigated (e.g., adapted filling scheme). Infrastructure behaving well since then. Note: extensive monitoring in place.
- Note 15:** Stormwater Dike – Internal dike experienced movement larger than expected after construction. Movement stabilized with help of adapted filling scheme. Now confine with tailings on both sides.
- Note 16:** NRF1 – Seepage observed through rockfill dike NRF1 in 2013. To mitigate, filling scheme was modified, and filter material added. Issue has been resolved.
- Note 17:** Central Dike – Higher seepage than originally anticipated by the design. Mitigation measures put in place to address the flowrate (e.g., pumping capacity increased). Situation stable for last seven years. Note: extensive monitoring in place.

### GOLDEX

- Note 18:** Southwest Dike – No known stability issues.
- Note 19:** Internal Dike – Experienced movement in 2011. Mitigation measures implemented in 2011 to address the issue. Since then, no issue encountered, but still needs to be upgraded to meet evolving design criteria.
- Note 20:** Southeast Dike – No known stability issues.

### LARONDE

- Note 21:** Dike 1 & 7 – The dikes are at final elevation and no more slurry tailings will be deposited within the Main Tailings Facility. Dike 1 originally constructed in 1988. Mitigation measures implemented over time either to meet evolving design standards or to address observed issues. The dike design migrated from a centreline construction to an upstream construction to reduce risks and has been behaving well for many years. Note: extensive monitoring in place.
- Note 22:** Dike 2 – Dike 2 started as an external dike and became an internal dike. Dike 2 experienced excessive seepage early on (1988-1993). It was raised over time with limited head difference between upstream and downstream and behaved well afterward.
- Note 23:** Dike 10 – No more slurry tailings will be deposited within the Extension A4 Facility. Review of stability of Dike 10 is completed and mitigation stability berm implemented to meet the minimum required factor of safety of 1.5.

### CANADIAN MALARTIC

- Note 24:** Starter Berm West – Dike constructed in 2012 by a different owner on an existing site dating back before the 1990s. No noticeable stability issue but was upgraded with time to meet evolving design criteria.
- Note 25:** Dike 5 – Dike constructed in the 1990s by a different owner. No noticeable stability issue but was upgraded with time to meet evolving design criteria. Some movement in the foundation has occurred over the last 5 years but it has stabilized and is being monitored closely. Stability berms were constructed in March 2021 to improve factor of safety from 1.4 to 1.5. Note: extensive monitoring in place. The starter dam of Dike 5 is now buried inside of PR7.
- Note 26:** Starter Berm Central – Dike constructed in 2012 by a different owner on an existing site dating back before the 1990s. No noticeable stability issue but was upgraded with time to meet evolving design criteria.
- Note 27:** Dike C – Constructed originally as a water retention dam (e.g., to keep water to the south out of the TSF and operations) with upstream face on south. Over time, the northern land area was filled with tailings, and it is now a tailings dike with downstream raises. Two stability shear keys of 20m and 10m wide were built in March 2021 and January 2022, respectively, by excavation of the clay and replacement with rockfill to reduce the risks associated with clayey foundations.
- Note 28:** Starter Berm East – Dike constructed in 2012 by a different owner on an existing site dating back before the 1990s. No noticeable stability issue but was upgraded with time to meet evolving design criteria.
- Note 29:** Dike North – Dike constructed in the 1960s-1970s by a different owner. No important issues but was upgraded in 2015 to meet evolving design criteria and is now an encapsulated internal structure.
- Note 30:** Dike South – Dike constructed in the 1960s-1970s by a different owner. No important issues but was upgraded in 2015 to meet evolving design criteria and is now an encapsulated internal structure.
- Note 31:** PR7 – A 60m wide stability shear key was built between February and July 2022 by excavation of the clay and replacement with rockfill to reduce the risks associated with clayey foundations.

## MACASSA

**Note 32:** In 2018/2019 some of the perimeter dikes were stabilized to improve their performance under seismic conditions. Shear keys were installed in Upper Dam B and Upper Dam E (using soil mixing) and in Lower Dam B (by foundation excavation and replacement with rockfill). Additionally, downstream rockfill berms were constructed on Dams/Dikes Upper B, Lower B, E, Lower E, F and G.

## HOLT

**Note 33:** In 2020/2021, the perimeter Dikes 1, 2, 2A, 3, 3A, 4, 8 North and 8 South were stabilized with downstream rockfill shear keys and buttresses.

## KITTILÄ

**Note 34:** NP3 West Dam – A leak event of non-contaminated water occurred in 2015 through the base layer of the liner. The leak was rapidly contained and plugged and required a change from downstream construction method to an upstream construction to reduce further risks. Issue resolved.

## FOSTERVILLE

**Note 35:** CIL Hardstand #1 – Potential instability of the Section, however the facility does not have a pond and the phreatic level within the facility is low. Any potential failure would likely fall onto the adjacent Hardstand 4 pad, which has been recently constructed. The Section is also considered temporary as Hardstand 4 will start to receive tailings within Q3 2023, resulting in encapsulating and buttressing of the Section.

## PINOS ALTOS

**Note 36:** Pinos Altos TMF – During start-up (2008-2010), filtered tailings deposited at the base of the stack had a slightly higher water content than considered in design. Mitigation (prefabricated vertical drains and improved construction methods) successfully applied to promote dewatering of filtered tailings and reduce potential for displacement. Issue resolved and facility is now going through final closure.

**Note 37:** Tailings are filtered, compacted and confined in open pit, release outside of pit is not possible.

## INACTIVE SITES

**Note 38:** Joutel North Dike – Site is inactive and being reclaimed. Experienced some minor issues over time during operation that required the implementation of mitigation measures. Since the end of operation, it has been behaving well.

**Note 39:** Joutel East Dike – Site is inactive and being reclaimed.

**Note 40:** Joutel South Dike – Site is inactive and being reclaimed. Experienced some minor issues over time during operation that required the implementation of mitigation measures. Since the end of operation, it has been behaving well.

**Note 41:** Camflo TSF – Site is inactive and in care and maintenance. Active water management required. Hydrology review completed in 2022 and geotechnical review in progress.

**Note 42:** Cobalt Nova Scotia Retaining Berm – Historical site, reclaimed in the 1990s. Over the years this infrastructure required some minor mitigation measures. Issues were resolved and the site has been behaving well for several years.

**Note 43:** Kirkland Minerals – Historical site (closed over 60 years ago), acquired with limited historic information. Engineering studies for the stabilization of these dams are underway and stabilization work is anticipated in 2023/2024.

**Note 44:** Upper Canada – Site is inactive and being reclaimed.

**Note 45:** Bidgood – Site is inactive and being reclaimed.

**Note 46:** Cosmo Howley Tailings Facility – Site is inactive and being reclaimed. In 2022, reclamation efforts included removal of ponds within the impoundment footprint and removal of dam embankments. As a result, these are no longer classified as dams and are removed from annual inspection requirements. Spillways at dams 2, 3 and 7 have been upgraded in 2022 as well and it is understood that the dams will be handed over to the local pastoralists.

**Note 47:** Union Reefs – Site is inactive, in care and maintenance, and being reclaimed. In 2022 reclamation efforts included spillway upgrades at the TSF, which are expected to be complete in 2023, and general vegetation clearing.

**Note 48:** Pine Creek – Site is inactive and closed. In 2022 no significant works were completed, and minor work included removal of spoil piles on the upper cell and cleaning up of the spillway channel.

# Appendix A: Tailings: A By-Product Of Mining & Mineral Processing

*Paste backfill plant, Goldex mine, Quebec.*


Mines with conventional ore processing facilities produce “tailings” that must be properly managed and stored to protect the public and the environment. Mining activities mainly encompass the following stages:

**Extraction (1)**, which is accomplished by blasting and excavating rock that is encasing the ore (e.g., waste) and the ore itself;

**Crushing (2)**, where the ore is fragmented by mechanical means to the required size for mechanical transfer to the processing facility;

**Comminution (3)**, where the rock fragments are ground to fine particles (e.g., silt size) to allow the liberation of the valuable metals and minerals (e.g., gold); and

**Metals and Mineral processing (4)**, where the valuable mineral (e.g., gold) is separated and concentrated by either mechanical means (e.g., gravity circuit) or chemical means (e.g., flotation or cyanidation). Somewhere in the process, water is added to the fine particles of rock to facilitate mineral processing and transport as a slurry.





## Appendix B: Definitions – Types of Tailings

*LaRonde complex commissioned its new filtered tailings storage facility in the second half of 2022.*

**Slurry:** Mixture of finely ground rock and water: solid content between 20% and 45%.

**Thickened:** Mixture of finely ground rock and water, after a thickening process: solid content between 45% and 60%.

**Paste:** Mixture of finely ground rock and water, after thickening and the addition of a binding agent: solid content between 60% and 75%.

**Filtered:** Mixture of finely ground rock and water, after filtering: solid content higher than 75%.

### Note:

These solid content ratios are given for illustrative purposes and may vary depending on the type of tailings.



Thickened tailings at  
Canadian Malartic mine, Quebec



In-pit filtered tailings deposition at Pinos Altos  
Oberon-de-Weber pit, Mexico.


# Appendix C: Tailings Storage Facility Risk Evaluation Methodology and Results

*Detour Lake Mine, Ontario. Construction of downstream rockfill for Stage 3 raising at TMA Cell 2 in June 2022.*

Risk assessment serves two main purposes: 1) as a means of communicating the level and nature of risks associated with specific TSF and the TSF portfolio to management from mine operation to ownership level as well as other stakeholders; and 2) to provide detailed, quantitative data that can be used to prioritize risk management measures that correspond to actionable elements of design, construction, operation and monitoring. This section introduces the simple, yet robust risk assessment methodology applied to each tailings storage infrastructure and facility, specifically designed for compiling information, then measuring, understanding and communicating relative levels of risk for complex critical mine infrastructure whose design and construction evolve over an extended period of time.

In general, the evaluation is broken into several steps, and involves the use of empirical relationships developed between annual probability of failure (APF), factor of safety (FS) and level of practice (LOP), as shown in Figure A, alongside the well-recognized published work of Silva et al. (2008), which formed the basis of this updated method.

**Figure A: Factor of Safety vs. Annual Probability of Failure a) Chovan, et al. (2020, 2021) and b) adapted from Silva, Lambe & Marr (2008)**



For each infrastructure, the following steps were taken:

1. Evaluate each of the Level of Practice (LOP) criteria and select appropriate ratings. The LOP criteria are divided into six categories of practice: 1) Design-Investigation; 2) Design-Laboratory testing; 3) Design-Analysis; 4) Construction; 5) Operation & Monitoring, and 6) Performance. For each category, the infrastructure were evaluated and rated as I, II, III or IV, corresponding to High, Good, Average or Low, respectively. Appropriate scores were assigned for each criterion according to its respective LOP rating.
2. With each criterion having equal weight, the scores of the criteria were then summed to obtain a total score for the infrastructure, where final scores of 1.0, 2.0, 3.0 and 4.0 are associated with High, Good, Average and Low Level of Practice.
3. As part of the design and analysis process, multiple stability analysis have been performed on all infrastructure, which determines Factor of Safety (FS) for specific construction and operating conditions. The FS selected for the evaluation was from the most credible failure mechanism associated with a potential failure of the infrastructure, and that associated with static conditions in drained or undrained conditions, whichever is relevant for the section.
4. With the LOP and the static FS, the Annual Probability of Failure (APF) was derived using the modified FS-LOP-APF relationships in Figure Aa.
5. Consequences of failure are assessed for the infrastructure assuming it will fail completely and independently of its actual probability for failure. Review of the dam-break and run-out analyses facilitates determination of the appropriate potential consequences, in four categories: health and safety, financial, environmental, and community. The potential consequences considered per consequence rating are described in Tables A through C.
6. Lastly, the APF is plotted against the infrastructure's consequence rating to determine its appropriate risk category.

As can clearly be seen in the figures, the results of the full evaluation allow prioritization of risk mitigation plans and actions across the company's portfolio of critical infrastructure, including tailings, water and heap leach management facilities. Details regarding the development and implementation of the evaluation process, updates made to the Silva method, and the evaluation criteria, can be found in Chovan, et al. (2020, 2021).

## References:

- Chovan, K., M. R. Julien, É.-P. Ingabire, E. Masengo, T. Lépine, M. James, & P. Lavoie (2020). Risk assessment for tailings management. *CIM Journal*, 12(1), 9-24. <https://doi.org/10.1080/19236026.2020.1866336>
- Chovan, K., M. R. Julien, É.-P. Ingabire, M. James, E. Masengo, T. Lépine, & P. Lavoie (2021). A risk assessment tool for tailings storage facilities. *Canadian Geotechnical Journal*. 58(12): 1898-1914. <https://doi.org/10.1139/cgj-2020-0329>
- Silva, F., Lambe, T. W., & Marr, W. A. (2008). Probability and risk of slope failure. *Journal of Geotechnical and Geoenvironmental Engineering*, 134(12), 1691-1699. [https://doi.org/10.1061/\(ASCE\)1090-0241\(2008\)134:12\(1691\)](https://doi.org/10.1061/(ASCE)1090-0241(2008)134:12(1691))

**TABLE A: CONSEQUENCE RATINGS FOR HEALTH & SAFETY, AND FOR MATERIAL DAMAGE**

Category/ Rating	Consequences: Health & Safety		Consequences: Material Damage
	Injury or Illness	Health Effects	
<b>Extreme/ Critical (5)</b>	<ul style="list-style-type: none"> <li>Single or multiple fatalities.</li> <li>Permanent disability to several people after a tragic event.</li> </ul>	<ul style="list-style-type: none"> <li>Single or multiple fatalities or serious disabling illness to multiple people.</li> <li>Includes illnesses such as lung diseases, lung cancer, silicosis, skin disease.</li> </ul>	<b>&gt; \$50 M</b>
<b>Major (4)</b>	<ul style="list-style-type: none"> <li>Permanent disability (e.g., loss of limb, burns &gt;50% of body).</li> </ul>	<ul style="list-style-type: none"> <li>Irreversible health effects or disabling illness.</li> <li>Includes substantial loss of normal function (i.e., hearing loss, loss of mobility).</li> </ul>	<b>\$5 M to \$50 M</b>
<b>Moderate (3)</b>	<ul style="list-style-type: none"> <li>Severe, reversible physical effect of concern that would typically result in a lost time illness.</li> <li>Temporary disability (e.g., fracture, sprain, burn &lt;50% of body). Worker will recover full physical integrity.</li> </ul>	<ul style="list-style-type: none"> <li>Severe, reversible health effect of concern that would typically result in a lost time illness.</li> <li>Includes acute/short-term effects associated with temperature, hearing, mobility and other normal activities.</li> <li>Psychosocial stressor would likely fall in this category.</li> </ul>	<b>\$1 M to \$5 M</b>
<b>Minor (2)</b>	<ul style="list-style-type: none"> <li>Reversible physical effects of concern that would typically result in medical treatment.</li> <li>Medical treatment.</li> <li>No lost time or occupation illness.</li> </ul>	<ul style="list-style-type: none"> <li>Reversible health effects of concern that would typically result in medical treatment.</li> <li>Includes musculo skeletal, vibrations effects, infectious diseases and sunburn.</li> </ul>	<b>\$500 K to \$1 M</b>
<b>Negligible (1)</b>	<ul style="list-style-type: none"> <li>Reversible physical effects of little concern, requiring first aid treatment at most.</li> <li>First aid.</li> </ul>	<ul style="list-style-type: none"> <li>Reversible health effects of little concern resulting from an exposure to a stressor.</li> <li>Includes minor irritations of eyes, throat, nose and or skin. Minor muscular discomfort.</li> </ul>	<b>&lt; \$500 K</b>

**TABLE B: CONSEQUENCE RATINGS FOR ENVIRONMENT**

Category/ Rating	Consequences: Environment			
	On Ecosystems	On Land Use	On Water	Cost of Remediation / Legal & Other Requirements
<b>Extreme/Critical (5)</b>	Physical Extent: Consequence extends outside site boundary; and  Consequence on wildlife: Habitat destruction, endangered species affected, including death of animals; recovery would take more than 5 years; and/or  Duration of effect: Remediation would take more than 5 years before returning the area to its previous state and use. May be irreversible.	Consequence on private or community properties requiring evacuation because of contamination of surface or air emissions.  Land subsidence: Offsite large scale.	Consequence on surface water: Affects major water course inhabited by fish, resulting in fish death; and/or  Consequence on groundwater: effect on important aquifer affecting long-term water quality, rendering it unusable long-term for water supply.  Duration of effect: More than 5 years water quality impairment.	Cost: More than \$50 M including fines, compensation, acquisition and clean-up; and/or  Regulatory Compliance: Suspension of operating permit indefinitely (> 6 months).
<b>Major (4)</b>	Physical Extent: Consequence extends up to 1 km of site boundary; and  Consequence on wildlife: Habitat destruction and/or animal death, recoverable within 1-5 years; and/or  Duration: Remediation would take 1-5 years before returning area to its previous state and use. Some long-term consequence will remain.	Consequence on private or community properties requiring remediation (surface only).  Requiring informing the population (ex: air emission).  Land subsidence: Offsite minor or localized scale. On site land subsidence.	Consequence on surface water: Affects major water course inhabited by fish, but no fish death, only impairment to water quality; and/or  Consequence on groundwater: Effect on important aquifer affecting water quality, rendering it unusable for water supply; and/or  Duration of effect: Recoverable in less than 5 years.	Cost: Between \$5 M and \$50 M including fines, compensation, acquisition and clean-up; and/or  Regulatory Compliance: Legal non compliance with possible infraction notice. Temporary suspension of operating permit (< 6 months).  Compliance order.
<b>Moderate (3)</b>	Physical Extent: Consequence limited on site but could extend outside in close vicinity of site boundary; and  Consequence on wildlife: Habitat affected but recoverable in less than 1 year; and/or  Duration: Remediation would take less than 1 year before returning area to its previous state (reversible).	Minor consequence on private and community properties except on water supply but potential consequence on onsite infrastructure.	Consequence on surface water: Discharge to watercourse with minor consequence; and/or  Consequence on groundwater: Effect on local aquifer even outside the site.  Duration of effect: Recoverable in less than 1 year.	Cost: Between \$1 M and \$5 M including possible fines, compensation, acquisition and clean-up; and/or  Regulatory Compliance: Possible infraction notice (exceedance of effluent limit, air emission limit, etc.).
<b>Minor (2)</b>	Physical Extent: Consequences only inside the site boundaries. Affected area < 1000m <sup>2</sup> (soil contamination); and  Duration: Remediation can be done within 1 week (reversible).	Minor or temporary consequence on private or community properties.	None	Cost: Between \$500 K and \$1 M; and/or  Regulatory Compliance: Isolated legal non compliance or administrative non compliance (ex: sample missing); and/or  No legal consequence; and/or  Internal System Compliance: Non compliant with RMMS requirements.
<b>Negligible (1)</b>	Physical Extent: Consequences only inside the site boundaries. Affected area: few meters in diameter; and  Duration: Remediation can be done the same day (reversible).	No consequence on private or community properties.	None	Cost: Less than \$500 K, done within operational budget; and/or  Regulatory Compliance: Compliant  No legal consequence  Internal System Compliance: Compliant

**TABLE C: CONSEQUENCE RATINGS FOR COMMUNITY**

Category/ Rating	Consequences: Community		
	On the Social Acceptability by Stakeholders (Communities, Governments, Investors, etc.)	On the media image	On the private or public element, or cultural element
<b>Extreme/ Critical (5)</b>	<p>Trust: Direct loss or lack of trust and significant loss of political or community support that may lead to organized and systematic opposition.</p> <p>Impact for the site: Resort to the courts and injunction obtained for the termination of operations by opposition groups (e.g., roadblocks).</p> <p>Impact for the company: Investment deemed high risk by investors and lower share price; Permit application questioned by authorities and communities elsewhere in the world.</p> <p>Duration: Extended conflict (&gt; 1 year) Extent of Impact on Reputation: International Extent of community impact: &gt; 1 community</p>	Reputation – Media Exposure (International)	<p>Irreparable damage to a site or item of international importance (e.g., Glaciers, UNESCO World Heritage Site, important archaeological site); and/or</p> <p>Destruction of several public / private buildings; and/or</p> <p>Uncertain if the situation can be corrected or compensated.</p>
<b>Major (4)</b>	<p>Trust: Significant decrease in political or community support leading to numerous complaints to the authorities.</p> <p>Impacts on the site: Temporary interruption of operations; suspension of construction activities.</p> <p>Impact on the company: Investment considered risky by the investors.</p> <p>Duration: Conflict over several months Extent of Impact on Reputation: National Extent of community impact: 1 community</p>	Negative media coverage at the national level.	<p>Damage difficult to repair (the effects will remain significant) on a site or element of national importance (e.g., burials); and/or</p> <p>Irreparable damage to several public / private buildings; and/or</p> <p>Requires considerable effort to be corrected or compensated (no external process or mechanism in place).</p>
<b>Moderate (3)</b>	<p>Trust: Decreased political or community support and potential impact on immediate neighbours' support leading to formal complaints to site leaders.</p> <p>Impact for the site: Investigations by the authorities leading to the stoppage of some works; bad regional reputation affecting short-term recruitment.</p> <p>Impact for the company: Influence of media coverage on ESG agencies' assessment of Agnico Eagle's performance.</p> <p>Duration: Conflict over a few weeks Extent of Impact on Reputation: Regional Extent of impact on the community: A few dozen people</p>	Negative media coverage at the regional level.	<p>Damage to a site or element of cultural significance (archaeological sites) or to several public / private property; and/or</p> <p>Needs moderate effort to be corrected or compensated (appeals to an external mechanism, no process established).</p>
<b>Minor (2)</b>	<p>Trust: Complaints or informal concerns raised verbally by stakeholders and answered in a matter of days.</p> <p>Impact on the site: Need to obtain a resolution or an answer to the complaints formulated so that the situation is quickly resorbed. Communicate the resolution.</p> <p>Impact for the company: Could affect our ESG ranking.</p> <p>Duration: A few days Extent of Impact on Reputation: Local Extent of impact on the community: Some individuals</p>	Negative media coverage at the local level (e.g., complaint by stakeholder or community).	<p>Irreparable damage to a site or element of low cultural significance or to some public / private property; and/or</p> <p>Requires limited effort to be corrected or compensated (appeals to an internal mechanism, process already established).</p>
<b>Negligible (1)</b>	<p>Trust: The impact should not extend beyond the boundaries of the site, so should not affect the community.</p> <p>Impact on the site: No lasting impact</p> <p>Impact on the company: No impact</p> <p>Duration: &lt;1 day Extent of Impact on Reputation: None Extent of impact on the community: 1 individual</p>	Proportion of neutral pos / neg on social media or traditional media (e.g., public awareness may exist, but no concern on the part of the general population).	<p>Damage to a site or element of low cultural significance or public / private good; and/or</p> <p>Needs little effort to be corrected or compensated (appeals to an internal mechanism, process established).</p>



# Appendix D: Forward-Looking Statements:

*Goldex mine South Parc, Quebec.*

The information contained in this Summary of Tailings Management has been prepared as at April 28, 2023. Certain statements contained in this Summary of Tailings Management constitute “forward-looking statements” within the meaning of the United States Private Securities Litigation Reform Act of 1995 and “forward-looking information” under the provisions of Canadian provincial securities laws and are referred to herein as “forward-looking statements”. Such statements include, without limitation: statements regarding Agnico Eagle’s plans with respect to the design, construction, operation and closure of TSFs, including with respect to the implementation of best available and applicable practices. Such statements reflect Agnico Eagle’s views as at the date of this Summary of Tailings Management and are subject to certain risks, uncertainties and assumptions, and undue reliance should not be placed on such statements. Forward-looking statements are necessarily based upon a number of factors and assumptions that, while considered reasonable by Agnico Eagle as of the date of such statements, are inherently subject to significant business, economic and competitive uncertainties and contingencies. The material factors and assumptions used in the preparation of the forward-looking statements contained herein, which may prove to be incorrect, include, but are not limited to, the assumptions set forth herein and in management’s discussion and analysis (“MD&A”) and Agnico Eagle’s Annual Information Form (“AIF”) for the year ended December 31, 2022, filed with Canadian securities regulators and that are included in its Annual Report on Form 40-F for the year ended December 31, 2022 (“Form 40-F”) filed with the SEC. Many factors, known and unknown, could cause the actual results to be materially different from those expressed or implied by such forward-looking statements. For a more detailed discussion of such risks and other factors that may affect Agnico Eagle’s ability to achieve the expectations set forth in the forward-looking statements contained in this Summary of Tailings Management, see the AIF and MD&A filed on SEDAR at [www.sedar.com](http://www.sedar.com) and included in the Form 40-F filed on EDGAR at [www.sec.gov](http://www.sec.gov), as well as Agnico Eagle’s other filings with the Canadian securities regulators and the SEC. Other than as required by law, Agnico Eagle does not intend, and does not assume any obligation, to update these forward-looking statements.

# Appendix E: Revisions

*Reforestation at Pinos Altos, Mexico.*

This appendix lists and tracks the revisions made to this document since the release of the 2019 Tailings Summary Report.

Document version	Date	Page	Revisions
REVISION 1	July 12, 2019	1	Addition of text referring to Appendix D: Revisions
		8	Meliadine table – columns 2 and 3, line 2: Addition of thousands separators to the tailings volume numbers. 89000 is now 89,000 and 4354000 is now 4,354,000
		11	Kittilä Table – Typo in column 4, line 4: CL2 corrected to CIL2.
		11	Kittilä Table – Typo in column 2, line 8: CL2 corrected to CIL2.
		11	Kittilä Table – Error in facility's name and associated Max Capacity in column 1, line 7: CIL1 TSF corrected to CIL2 TSF and Max Capacity of 65,220 m3 corrected to 5.4 Mm3
		12	LaRonde table – Column 10, line 4: missing word. Upstream corrected to Upstream raise
		22	Addition of APPENDIX D: REVISIONS to list and track revisions made to this document since its initial release on June 7, 2019.
REVISION 2	April 30, 2021	1	Changed Appendix D to Appendix E
		1–6	Sequence of report revised and updated:  General removal of references to MAC and ICMM updates to their tailings management standards and guides throughout, keeping focus on Agnico Eagle's activities to meet or exceed such standards (pgs 2–3 2019).  Reorganized and consolidated parts of "Strengthening our Tailings Governance for Safe & Responsible Operations" and "Incorporating Best Practices" from 2019 report (pgs 1–2 2019) into one section on pg 2 (now).  Renamed, moved and updated "Employing Best Applicable Practices" (pg 5 2019) to "Incorporating Best Applicable Practices" (now pgs 2–3).  "Striving to Meet or Exceed Current Standards & Practices" moved from pg 3–4 (2019) to pgs 4–5 (now) and includes reference to updated disclosure tables and risk evaluation results.
		7–14	Updated, reorganized and replaced tables and notes (pgs 7–18 2019) for Tailings Storage Facilities. New tables and notes now fill pgs 7–14, and include additional risk evaluation details. Updated risk evaluation method and consequence ratings tables moved to new Appendix C.
		17–21	Addition of Appendix C: Tailings Storage Facility Risk Evaluation Methodology and Results, including two new figures to provide visual representation of risk evaluation results and updated consequence ratings charts in Tables A through C.
		22	Changed title of initial Appendix C to Appendix D and updated content.
		23	Changed title of initial Appendix D to Appendix E and added 2021 revisions to the table.
REVISION 3	April 30, 2023	1–2	Generally updated to include operations acquired through merger with Kirkland Lake Gold.
		4	Updated referenced page numbers of tables containing disclosed information for all TSFs, as well as inclusion of ANCOLD as a guideline.
		6	Updated list of research activities and associated images
		7–26	Updated and replaced tables and notes (pgs 7-14 2021) for Tailings Storage Facilities. New tables and notes now fill pgs 7-26 and include all closed sites and facilities acquired.
		27–36	Page numbers revised & addition of 2021 published journal article as a reference in Appendix C, pgs 29 & 30.
		35	Added 2023 revisions to this table in Appendix E.



**AGNICO EAGLE**

Agnico Eagle Mines Limited  
145 King Street East, Suite 400  
Toronto, Canada M5C 2Y7  
[agnicoeagle.com](http://agnicoeagle.com)